Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0065**

Resource Identification

Property Name(s): ..... Hall Farm {Current}
Property Date: 1830
Address(s): ..... Route 621 {Current}
County/Independent City: Isle Of Wight
Vicinity of: ..... Moon Eght
State, Zip: .....Virginia
USGS Quad Name: ..... RUNNYMEADE

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Component Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Exterior end	Brick	other
Chimneys	other	Brick	
Foundation	Foundation - Solid	Brick	other
Porch	Porch - 1-story, 1-bay	Wood	other
Roof	Roof - Gable	Asphalt	Roof - Shingle
Roof	Roof - Gable	Wood	other
Structural System	Structural System - Frame	Wood	other
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6
Windows	Windows - Sash, double-hung	Wood	Windows - 6/9

WUZIT Count:

No.	Wuzit Types	Historic?
1	Single Dwelling	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Single Dwelling

Est. Date of Construction: .... 1830 ca {VDHR Survey File}
Accessed? ..... Yes
Primary Resource? ..... Yes
Number of Stories: 1.5
Interior Plan Type: ..... Central Passage, Double Pile
Threats to Resource: ..... Vacant

Description: Architecture Summary: Three-bay, 1.5-story dwelling with 3 gable dormers on each slope of the gable roof. 1-story rear additions. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: The interiors are characterized by the extensive use of wainscotting on the first floor and a simple chair rail on the second. End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information: *(Intensive Level Survey)*

Historic Context(s): ..... Domestic

Bibliographic Documentation

Report generated 11/17/04

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0065**

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			1973/10/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,

Cultural Resource Management Event: ..... Intensive Survey
Date: 1973/10/99
Organization or Person: ..... Bernard Herman
CRM Event Notes or Comments: .....

VIRGINIA
HISTORIC LANDMARKS COMMISSION
SURVEY FORM

46-65
File Number

1. County Isle of Wight
   Town vicinity Moonlight
   Street No. rt 621

   USGS Quad Name Runnymede, Va.
   Quad Date 1968
   Original Owner
   Original Use dwelling
   Present Owner Earl Hall
   Present Owner Address Surry, Va.

   Present Use abandoned

2. Historic Name
   Present Name Hall Farm
   Date or Period (exact or estimate) circa 1830
   Architect
   Builder, craftsman, etc.
   Source of Name
   Source of Date construction

3. No. stories (dormers count as ½ story):
   1½
   Wall construction
   frame
   Acreage approx 5 acres

4. Historical Significance (Chain of Title, Families and Events, etc., connected with the property)

5. Architectural Significance (Note interesting interior and exterior details, etc., cite significant alterations and additions)

A frame structure of one and a half stories, the Hall Farm house is built on a double pile center hall plan. Although the original beaded siding has been replaced the exterior is still characterized by two large brick chimneys at either end of the house. The brickwork of the chimneys and foundations is three course American bond, and although the stacks have been rebuilt on two of the chimneys they still have their rough untiled weatherings.

The interiors are characterized by the extensive use of wainscote on the first floor and a simple chair rail on the second. The wainscote is unpaneled being built of unbeaded boards fitted together in a shiplap fashion. The mantels fit segmentally arched hearth openings and like the wainscote are shallowly paneled. Of additional note is the simple stair rail at the second floor landing: it being beaded and supported on simple unturned balusters ending in a capped newel post.

6. Physical Condition	Excellent	Good	Fair	Poor
Structure			X	
Grounds			X	
Neighborhood			X	

7. State potential threats to preservation of structure

Abandoned and vandalized

(over)

8. List Number of Photographs _____Exterior _____Interior _____Outbuildings

9. Sources and Bibliography:
   A. Published Sources (author, title, date, page number, etc.)

   B. Primary Sources (original or later drawings, old photographs, pictures, manuscripts and their location)

   C. Names and Addresses of People Interviewed

10. Name, Address and Title of Recorder:

bernard l herman/vhlc
Date of Record
October 1973

11. First Floor Plan (Rough Plan indicating arrangement of rooms, doorways, windows on ground floor)



12. Site Plan (Locate and identify outbuildings, dependencies, and significant farm structures)